



### Map 10. ARTHUR CHASE TRAIL INVENTORY AND MAINTENANCE NEEDS

- Maintenance Needs (see table)
- Photo Locations

1	Trailhead is indistinct - needs better signage and blazing
2	Stream crossing difficult during high water
3	Steep area with erosion potential
4	Steep area with erosion potential
5	Stream crossing difficult during high water

Deerfield, NH Trail Inventory  
August 2011

