




# Map 5. DOWST-GATE TRAIL INVENTORY AND MAINTENANCE NEEDS

-  Maintenance Needs (see table)
-  Photo Locations

1	Decaying foot bridge - needs repair or removal
2	Trail indistinct - needs re-blazing



Deerfield, NH Trail Inventory  
August, 2011

